
Sharon High School Study

Sharon School Committee Report







Context




Construction/Renovation History



Existing Use Floor Plans



MSBA Square Footage Comparison







- Evaluation of Existing Conditions
 - Deferred Maintenance
 - Code Required Upgrades
- Educational Programming
 - Demographic Projections (level population projected)
 - Comparison to MSBA Guidelines (current bldg. undersized)
 - Evaluation of Curriculum vs Building Space Needs
- Options Development
 - Range from Addressing Deferred Maintenance to Educational and Community Upgrades to New Building including: 16 areas of the building proposed to be upgraded (not prioritized)




- Option 1: Deferred Maintenance and Code Required Upgrades
- Option 2: Includes Option 1 + 6 Priority Areas
- Option 2A: Includes Option 2 + 2 Additional Priority Areas
- Option 3: Option 1 + All 16 Building Areas
- Option 4: New High School Building



Building Enclosure:

- Brick Repair to prevent water infiltration
- Sealant replacement at windows, doors
- Replace '56 and '63 doors
- General repairs around doors, windows and floors caused by water infiltration





Exterior door systems showing portions of caulking completely missing



| Exterior door showing damaged floor tiles and threshold

Option 1: Deferred Maintenance and Code Required Upgrades



Building Exterior:



Northern courtyard breezeways with rusted structure



Courtyards in disrepair




Outdoor refrigerator

Option 1: Deferred Maintenance and Code Required Upgrades



Interiors and Finishes

- Repair / replace damaged flooring, ceiling panels
- Accessibility issues including: Rework slope of ramps, some toilet rooms,



Patched or mismatched floor tile infill



Damaged and mismatched ceiling panels



Bowing ceiling tile due to high level of humidity


Option 1: Deferred Maintenance and Code Required Upgrades

Building Code:

- Seismic upgrades
 depending on level of
 work undertaken –
 analysis required
- Handicapped Accessibility
- Other



Non-compliant ramp



Option 1: Deferred Maintenance and Code Required Upgrades

Mechanical:

- Replace numerous air handling units
- Replace classroom unit ventilators
- Boiler replacement for efficiency
- Replace hot water pumps



roof mounted fume hood exhaust utility fan is in very poor condition and should be replaced.



air handling unit

Option 1: Deferred Maintenance and Code Required Upgrades



Plumbing / Fire Protection:

- Acid waste system upgrades
- Science lab systems upgrades
- Kitchen plumbing upgrades

Acid waste system is within a common storage room and has no ventilation or emergency shower







Electrical

- Replace 18 electrical panels
- Replace electrical circuits in '56 & 63 areas
- Replace power in kitchen
- Replace theatrical and house lights in auditorium
- Upsize emergency generator, add connections



Stage Panel





Panels that exceed useful life

Option 1: Deferred Maintenance and Code Required Upgrades



Technology:

- Telecommunication infrastructure upgrades
- Replace bells and slave clocks
- Improve electronic security systems
- Upgrade AC to head end room
- Add UPS for data rooms





Typical Original Classrooms

Option 1: Deferred Maintenance and Code Required Upgrades



- Item 1: Science, Properly size labs and prep
- Item 2: Creation of Technology Space(s)
- Item 3: Entry Sequence
- Item 4: Auditorium
- Item 5: Expansion of Music
- Item 6: Expansion of Art
- Item 7: Reconfigure
 Administration Suite

- ■Item 8: Expansion of Medical Suite
- ■Item 9: Relocation of Guidance
- ■Item 10: PE Complex
- •Item 11: Dining / Servery /

Kitchen

- ■Item 12: Typical Classrooms
- ■Item 13: Library Suite
- ■Item 14: TV Studio
- ■Item 15: Exterior Courtyards
- ■Item 16: SPED

All Program Items – No Priority

Item 1: Science, Properly size labs and prep for curriculum and safety:

- Construct a new 2 story science wing [27,360 GSF] for 11 labs and 5 prep rooms.
- new wing will be connected to the existing library (2nd floor) and existing elevator by a corridor[2,500 GSF] running on the west side of the existing auditorium
- Includes demo of existing 1 story classroom wing 8,200 sq.ft.

Item 2: Creation of Technology Space(s):

Working towards STEM:
 Renovate 4,000 nsf of the existing science labs into
 (2) STEM labs

Item 3: Entry Sequence:

Safety:

Construct a 500 GSF addition at the existing main entrance to accommodate a double vestibule entry sequence with an administration station to monitor the doors.

Item 4: Auditorium - Up to date, attractive, serve the school and community:

- Addition of a full stage fly
- Comprehensive renovation of the auditorium, stage and control room;
- Removal of the slab and stairs to re-profile the floor to an accessible configuration
- New rigging, new light and sound system
- New seating
- New acoustical treatment
- Improve access to existing catwalk

Item 5: Expansion of Music: To meet curriculum needs:

Remove existing music classroom (approx. 6,000 GSF), construct 6,000 GSF for 3 CR music suite

Item 6: Expansion of Art: To meet curriculum needs, preferably more central:

Comprehensive renovation including internal reconfiguration



Item 7: Reconfigure Administration Suite:

- Reconfigure for size and flow, tie to entry sequence in item (3)
- Expand the administration by appropriation of the auditorium storage and elimination of the corridor

Item 8: Expansion of Medical Suite:

 Reconfigure admin area to expand for larger medical suite including 600 GSF addition



Item 9: Relocation of Guidance: Closer to administration

- Renovate 3 classrooms into offices, conference etc for Guidance
- Renovate existing Guidance space into 2 classrooms and a Large Group Instruction space

Item 10: PE Complex: Right size, fitness for life, community use:

- Add a 3rd gym bay
- Add (2) alternative Gym spaces, Fitness and Dance / Exercise
- Renovate both locker room suites

Item 11: Dining / Servery / Kitchen: Right size:

- Multi-use of café, scramble servery, update & enlarge kitchen
- Comprehensive renovation to the kitchen and servery
- Building addition within the courtyard to right size the café



Item 12: Typical Classrooms: Update for:

- Acoustics, technology, furniture, appearance
- All classrooms (42)- acoustical isolation of demising partitions
- Cosmetics
- New marker boards, improve technology
- New furniture
- Classroom storage



Item 13: Library Suite: Update to meet current media center needs

- Modest renovation including reconfiguration to include 4 collaboration rooms
- Cosmetics
- Furniture
- Shorter stacks
- Technology



Item 14: TV Studio : Enlarge to meet curriculum needs and demand:

 Renovate / enlarge the existing TV studio to 2,000 nsf total

Item 15: Exterior Courtyards

- Enliven, Make more attractive and useful
- Add outdoor classroom to main courtyard


Item 16: SPED : Improve / increase # & sizes of spaces:


 Reconfigure / renovate areas throughout the school for varying sizes of classrooms, offices, support spaces

Option 2

- Item 1: Science, Properly size labs and prep
- Item 2: Creation of Technology Space(s)
- Item 3: Entry Sequence
- Item 4: Auditorium
- Item 12: Typical Classrooms
- **Item 16**: SPED








Option 2

Option 2A

- Item 1: Science, Properly size labs and prep
- Item 2: Creation of Technology Space(s)
- Item 3: Entry Sequence
- Item 4: Auditorium
- Item 5: Expansion of Music
- Item 11: Dining / Servery / Kitchen
- Item 12: Typical Classrooms
- Item 16: SPED



Option 2A

OPTION 3


- Item 1: Science, Properly size labs and prep
- Item 2: Creation of Technology Space(s)
- Item 3: Entry Sequence
- Item 4: Auditorium
- Item 5: Expansion of Music
- Item 6: Expansion of Art
- Item 7: Reconfigure
 - Administration Suite

- Item 8: Expansion of Medical Suite
- ■Item 9: Relocation of Guidance
- ■Item 10: New PE Complex
- •Item 11: Dining / Servery /


Kitchen

- ■Item 12: Typical Classrooms
- ■Item 13: Reconfigure Library Suite
- ■Item 14: Expansion of TV Studio
- ■Item 15: Exterior Courtyards
- **■Item 16**: SPED


Option 3 – All Program Items



Option 3







Context

Construction Costs

- Associated Project Costs
 - Construction Contingency

Bricks & Mortar

- OPM Fee
- General Contractor Fee
- General Conditions
- General Requirements
- Design Contingency
- Construction Escalation
- Construction for temporary Swing Space

- Designer Fee
- Other Consultants Fee
- Furniture & Equipment
- Technology Equipment
- Materials Inspection and Testing During Construction
- Owner's Contingency

- Utility Company
 Backcharges
- Owner's Insurance, etc.
- Legal Cost
- Moving Cost
- Printing Cost








Option Details	Option 1		or		Option 2	or	Option 2A	or		Option 3	or	0	ption 4
Description	All issues identified in existing conditions report			Option 1 plus items 1,2,3,4,12 & 16			Option 2 plus items 5 & 11		Option 1 plus all 16 items			New High School	
Base Construction Cost (ECC) (including siesmic upgrades)	\$	11,582,000		\$	40,744,000		\$ 55,643,000		\$	61,638,000		\$	78,624,000
ADA Upgrades ACM and PCB removal	\$	1,282,000		\$	1,156,300		\$ 1,128,130 \$ 2,031,177		\$	1,082,280		\$	- 2 021 177
Demolition Existing Building Opt 4	\$	2,031,177		\$	2,031,177		\$ 2,031,177 \$ -		\$	2,031,177		\$	2,031,177 1,198,650
ECC Subtotal	\$	14,895,177		\$	43,931,477		\$ 58,802,307		\$	64,751,457		\$	81,853,827
Escalation (4% per annum, assumes 2 years)	\$	1,191,614		\$	3,514,518		\$ 4,704,185		\$	5,180,117		\$	6,548,306
Design Contingency (10%)		inc			inc		inc			inc		\$	8,840,213
Construction Manager at Risk preminum (10%)	\$	1,608,679		\$	4,744,600		\$ 6,350,649		\$	6,993,157			N/A
Total Construction Budget	\$	17,695,470		\$	52,190,595		\$ 69,857,141		\$	76,924,731		\$	97,242,346
ECC per sq.ft.	\$	88.58		\$	235.69		\$ 310.57		\$	329.11		\$	445.25
Modulars	\$	1,690,000		\$	1,990,000		\$ 1,990,000		\$	3,471,333		\$	-
Associated Costs - Professional services, testing, furntiure,													
technology etc.	\$	4,423,868		\$	13,047,649		\$ 17,464,285		\$	19,231,183		\$	24,310,587
Total Project Budget \$ 23,809,338			\$	67,228,243		\$ 89,311,426		\$	99,627,247		\$	121,552,933	
Project Cost per sq.ft.	\$	119.18		\$	303.60		\$ 397.05		\$	426.24		\$	556.56
Estimated durations		5 years		2-3 years			3-4 years		3.5 years			2.5 + 1 yr demo/site	
All Costs in Feb 2014 Dollars													



Eligibility Period

Up to 270 Days



Upon Invite to Eligibility Period, Districts complete defined requirements within the timeframes listed above



- High School Facilities Study (in process)
- Submit Statement of Interest (SOI) 2015 submissions by April, decisions by October
- MSBA Eligibility Period: up to 270 days (10 months)
- MSBA Feasibility Study and Schematic Design: 10 months
- Town Support and Approval: 4 months?
- Design through Bidding: up to 12 months
- Construction: Varies on option 2 4 years

From March 2014 to Capital Project Completion = anticipated 6-8 years



Thank you Sharon High School

